

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 JEEP WRANGLER WILLYS | 130,357 KM

VIN: 1C4BJWAG8HL586008

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

Yes	Specs	GCC	130357	Kilometers	
Semi Loaded	Option Type	* 	3.6L	Engine	6
Four Wheel Drive	Drive	।∕ ⊜ । ।√⊡-।	Manual	Transmission	
Petrol	Fuel	<u>(</u>	SUV	Body Type	(<mark>E)</mark>
Exterior Color Red	Exterior Color	-	Alloy Wheels	Wheel Type	
2 Airbags	Number of Airbags	²⁰	Fabric Trim	Interior Trim	*
2 Keys	Number of keys	Ş	4 Seats	Seating Capacity	Â,
			1C4BJWAG8HL586008	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	~	Cruise Control	~
Steering Mounted Audio Controls	 Image: A start of the start of	Rear Defogger	~
Central Armrest	~	Steering Column Adjuster	~
Exteriors			
Fog Light Front	~	Halogen Headlights	~

Performance			
Hill Descent Control	 		
රී Safety & Security			
Traction Control	~	Airbag Driver Front	~
ABS	 Image: A start of the start of	Central Locking	~
Bluetooth Player	~	Infotainment System	 Image: A start of the start of
USB player	~		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed			
🕾 Exterior			
Doors condition			
Front left door	 	Front right door Panel: Light Scuffing < 50mm	(!)
Fenders Condition			
Left Fender	 	Right Fender	
Quarter Panels Condition			
Left Quarter Panel	 	Right Quarter Panel	 Image: A start of the start of
Front Bumper Condition			
Front Bumper	 		
Rear Bumper Condition			
Rear Bumper	 		
Hood Condition			
Hood Bonnet: Light Scuffing < 50mm, Low Visibility Dent < 30mm	(!)		
Trunk Condition			
Trunk	 		
Trunk conditon			
Trunk	 		
Pillars Condition			
Left A Pillar	 	Right A Pillar	
Right A to B Pillar	 	Left B Pillar	 Image: A start of the start of
Running Board Condition			
Left Running Board	 	Right Running Board	 Image: A start of the start of
Windshield Condition			

Front Windshield	~	Rear Windshield	~
Structural Assessment			
Chassis Condition	 	Apron	~
Boot Floor	~	Firewall Condition	~
Cowl Top	 	Head Light Support Condition	
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror	 Image: A start of the start of	Left Side Mirror	
Right Side Mirror	 		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	 Image: A start of the start of	Left Rear Alloy/ Rim	~
Right Front Alloy/ Rim	 	Right Rear Alloy/ Rim	~
Spare Alloy/ Rim Condition	 Image: A start of the start of		
Grill Condition	~	Monogram	 Image: A start of the start of
Window Glass	~	Wiper	 Image: A start of the start of
Panel Condition			
Rear Trunk Panel	 		

Engine & Transmission

Engine			
Engine Body	 Image: A start of the start of	Engine Performance	•
Engine Oil (Condition & Level)	 Image: A start of the start of	Exhaust System	
Radiator Condition	 Image: A start of the start of	Radiator Coolant	•
Battery			
Battery Terminal & Tightness	 		
Fuel System			
Fuel Tank	~		

Transmission Operation			
Gear Shifting	 Image: A start of the start of	Drive Axle	 Image: A start of the start of
4*4 Condition (If Applicable)	 Image: A start of the start of	Transmission Fluid	 Image: A start of the start of
Steering, Suspension & Brakes			
Steering			
Steering wheel	 Image: A start of the start of		
Brake System			
Parking Brake	 	Brake Master Cylinder	
Brake Disc & Brake Pad	 	Brake Fluid	
Pedals	 		
Suspension			
Shock Absorbers	~		

Electricals, Controls & Lights

Keys			
Master Key	~	Spare Key(s)	 Image: A start of the start of
Dashboard			
Instrument Panel	 		
Airbags			
Airbags	~		
Cruise Control	 	Infotainment Display	~
OBD Connector	~	Music System	
Lights			
Headlight	 Image: A start of the start of	Interior Lights	
Tail Light Cluster	~	License Plate Light	~
Fog Lights	~		
Air Conditioning			
	 	AC Switch	

AC System Leaks	~	Center AC Vent	
Front Right AC Vent	 Image: A start of the start of	Heater	 Image: A start of the start of
Rear Defogger	 	USB Charging Port	~
Power/ Manual Windows	~	Seat Heaters	~

▲ Interiors & Luggage

Dashboard And Instrument Panel	~	Central Console	~
Glove Box	~	Steering Wheel	~
Sunvisor	~	Seat Upholstery Passenger Seat: Minor Smudge/Cracks	!
Manual Seat Movement	~	Seat Belts	
Head Rest	~	Door Controls And Trim	~
Grab Handle	 	Carpet Rear Left Floor Carpet: Smudge / Fair Use Wear	(!)
Headliner	~	Rear View Mirror	~
Toolkit			

Tyres

Tyres Condition			
Left Hand Side Front Tyre	 	Left Hand Side Rear Tyre	~
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	~
Spare Tyre	 		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE